

PCC Pavement Rehabilitation with Hot Mix Asphalt

54th Annual Illinois Bituminous Paving Conference
December 11, 2013



Kevin Burke III, P.E.
Illinois Asphalt Pavement Association
burkeiii.kevin@comcast.net



Assistance Provided By




Tim Murphy, P.E.
TMurphy@murphypavetech.com



Jeff Blue, P.E.
JBlue@co.champaign.il.us



Asphalt Institute MS-17



- Chapter 2: Pavement Evaluation
- Chapter 9: Preparing PCC Pavements for HMA Overlays
 - Saw-Cut and Seal/Crack-Relief Layer
- Chapter 10: Fractured Slab Techniques
 - Rubblization/Crack (Break) and Seat
- Chapter 11: Overlay Design for Rigid Pavements
- Illinois Examples



PAVEMENT EVALUATION



Pavement Evaluation

- Functional Characteristics
 - Ride Quality
 - Surface Friction
- Condition & Distress Survey
 - Collection
 - Rating
- Structural Testing
 - Destructive
 - Non-Destructive
- Drainage



Pavement Management System

- Sections 45-3 and 45-4 of BLRS Manual
- ICT R27-087: Implementing Pavement Management Systems for Local Agencies: State-of-the-Art/State-of-the-Practice
- Agency Specific

PASER Condition Ranges					
Excellent		10 - 9	10 – 5:		
Very Good		8	Feasible for		
Good		7 – 6	pavement		
Fair		5 – 4	preservation		
Poor		3	4 – 1:		
Very Poor		2	Not feasible		
Failed		1	for pavement preservation		
PAVEMENT PASER CONDITION					

Figure 45-4A

CRS	Condition Ranges	0.0 0.4:
Excellent	9.0 - 7.6	9.0 – 6.1: Feasible for
Satisfactory	7.5 – 6.1	pavement preservation
Fair	6.0 - 4.6	6.0 – 1.0: Not feasible
Poor	4.5 - 1.0	 for pavement preservation


Excellent	100-86	100 - 65:
Very Good	85-71	Feasible for
Good	70-56	pavement preservation
Fair	55-41	64 - 0: Not feasible for pavement preservation
Poor	40-26	
Very Poor	25-11	
Failed	10-0	

Illinois Asphalt Pavement Assn.

Treatment Selection

- Proof Rolling
- Joint Condition
- Existing Surface
 - Grooved
 - Polished
- Unstable Slabs
- Patching
- Seating
- Undersealing








PREPARING PCC PAVEMENTS FOR HMA OVERLAY



Saw-Cut and Seal


- Repair Existing PCC
 - Clean and fill joints
- Locate and Reference Existing PCC Joints
- Place HMA Overlay
- Saw-Cut Directly above Referenced Joints
- Clean and Dry Saw-Cut
- Apply Sealant





Crack Relief Layer

- Open Graded HMA
- Reflective Crack Control Systems
 - Standard Specs Article 443
- 4.75 mm Polymerized HMA
 - Standard Specs Article 1030





FRACTURED SLAB TECHNIQUES



Crack & Seat



- Correct Drainage
- Crack PCC Slabs
 - "guillotine" hammer
 - 30" or less
- Seat Cracked PCC
 - 35-50 ton pneumatic roller
- Remove / patch soft areas
- Overlay with HMA



Rubblization

- Correct Drainage
- Test Strip/Pits
- Rubblize
- Roll
 - Final sizing
 - Lock in pieces
- Overlay with HMA





PAVEMENT DESIGN



Functional Overlay


- Policy Decision
- BLRS Manual Section 14-1.02(j)
 - Eligible for State and MFT Funding
 - Maximum 2" Overlay
- BLRS Manual Section 46-3
 - Eligible for Federal, State, and MFT Funding
 - Must Meet Certain Requirments
 - Maximum 3.75" Overlay





Structural Overlay

- BLRS Manual Section 46-4
 - Modified AASHTO
 - + Determine Requires Structural Number
 - + Assign Structural Number to Existing Layers
 - + Determine Overlay Thickness
 - Falling Weight Deflectometer
 - + Non-Destructive Test
 - + More Accurate
- BDE Manual Section 54-5.03
 - Mechanistic Only Available for Rubblization





PROJECT EXAMPLES



Robert Palmer Drive - Elmhurst




- 8" PCC Doweled Pavement
- Significant Joint Failure
- Loss of Friction
- Deteriorating Median
- Poor Cross Slope
- 5,000+ AADT



Robert Palmer Drive Investigation

- Drove project;
 - D- ride quality.
 - Loss of skid resistance.
- Walked project;
 - D cracked panels.
 - Rocking panels.
 - Failing joint materials.






Robert Palmer Drive - Opening Joint







Robert Palmer Drive - Opening Joint







Robert Palmer Drive -Recommendations

- Waterproofing
- Patching
 - 6' wide asphalt patches (curb to curb)
- Joint Preparation
- Cold Mill
 - Rumble median
 - Curb reveal
 - Butt joints
- Spot Mill High Spots
- HMA Overlay
 - ¾" polymerized sand mix level course- 2" HMA surface course overlay

 - Isolated saw and seal



Illinois Asphalt Pavement Assn.



Champaign County

- County Road 9 (East of Ludlow) (2005)
 - 9-6-9 Lane (West) and Aggregate Base Lane (East) Pavements from 1930's
 - 4" HMA Overlay
 - 2 miles
- County Road 9 (West of Ludlow) (2007)
 - 9-6-9 Lane (West) and Aggregate Base Lane (East) Pavements from 1930's
 - 5"HMA Overlay
 - 7 miles
- County Road 17 (2008)
 - 7" Jointed 22' Pavement from 1930's
 - 5" HMA Overlay
 - 8 miles



County Road 9 (East of Ludlow)

- Milled Both Sides
- Rubblized Concrete
- 4" HMA Overlay
- Poor Performance
 - Heavy Rain after Rubblization
 - No Drainage







County Road 9 (West of Ludlow)

- Edge Drains Installed Prior to Rubblization
 - Concrete Side Only
- Milled PCC side
- Modified Rubblized PCC (Less Effort)
- 3" HMA Binder Lift Over Rubblized Base
- Milled 1" of Flexible Lane
- 2" HMA N50 Surface over Both Lanes
- Good Performance (Issues on Flexible Base Side)



Illinois Asphalt Pavement Assn.



County Road 17

- Edge Drains Installed Prior to Rubblization
- Milled HMA on One side
- Rubblized PCC on One Side
 - Spec Modification 75% less than 12" in dimension – no fragment exceeding 16")
- 3" HMA Binder Lift Over Rubblized Base
- Milled 1" of Flexible Lane
- 2" HMA N50 Surface (Full Width)
- Excellent Performance



